



G:\My Drive\Epro Master Folder\Drafting\Details\Underslab\Geo-Seal 60\41.170.1 GEO-SEAL 60 UNDERSLAB ASSEMBLY REPAIR.dwg [Detail] December 29, 2020 - 3:32pm

AS A SUPPLIER OF FINISHED PRODUCTS ONLY, EPRO SERVICES, INC. DOES NOT ASSUME RESPONSIBILITY FOR ERRORS IN DESIGN, ENGINEERING OR DIMENSIONS. THE PROJECT TEAM MUST VERIFY ALL DIMENSIONS AND SUITABILITY OF DETAILS. THE PRODUCTS LISTED ARE TRADEMARKS OF EPRO SERVICES, INC.



1328 E. KELLOGG DRIVE  
 WICHITA, KS 67211  
 1-800-882-1896  
 EPROINC.COM

**Geo-Seal**<sup>®</sup>  
 Vapor Intrusion Barrier



DRAWING NUMBER

**41.170.1**

SYSTEM NAME

**GEO-SEAL 60**

SYSTEM DESCRIPTION

**UNDERSLAB  
 ASSEMBLY REPAIR**

DATE

**12/29/2020**

DRAWN BY

**RJT**

SCALE

**NTS**

**PAGE 1 OF 1**