



G:\My Drive\Epro Master Folder\Drafting\Details\Underslab\Novatak\50.170.2.3 UNDERSLAB ASSEMBLY - REPAIR - PUNCTURE TEARS 2 INCHES OR GREATER (REINFORCED SEAM).dwg [Detail] July 01, 2021 - 8:18am

UNDERSLAB ASSEMBLY - REPAIR - PUNCTURES / TEARS 2" OR GREATER REINFORCED SEAM

	SYSTEM NAME	DRAWING NUMBER	
	NOVATAK	50.170.2.3	
	DRAFTER	DATE	
	RJT	6/21/2021	

AS A SUPPLIER OF FINISHED PRODUCTS ONLY, EPRO SERVICES, INC. DOES NOT ASSUME RESPONSIBILITY FOR ERRORS IN DESIGN, ENGINEERING OR DIMENSIONS. THE PROJECT TEAM MUST VERIFY ALL DIMENSIONS AND SUITABILITY OF DETAILS. THE PRODUCTS LISTED ARE TRADEMARKS OF EPRO SERVICES, INC.

NTS

PAGE 1 OF 1